# PRESERVED COACHING STOCK OF BRITISH RAILWAYS

## **AMENDMENT SHEET NUMBER 5**

July 1995

### 1) Additions

a) Mark 2 Passenger Carrying Coaching Stock

FK 13550 7550 Nottingham Sleeper Company, Elkesley, near Retford

### 2) Movements

a)	Mark	1	Passenger	Carry	ving	Coaching	Stoc
a)	IVI al N	1	1 assenger	Carry	ушg	Coacining	Sio

RMB	1878	Cheddleton Railway Centr	e				
TSO	4989	The Railway Age, Crewe	Stored at Gresty Green Sidings				
FK	13331	The Railway Age, Crewe	Stored at Gresty Green Sidings				
b) Mark 2 Passenger Carrying Coaching Stock							
TSO	5449	The Railway Age, Crewe	Stored at Gresty Green Sidings				
TSO	5462	The Railway Age, Crewe	Stored at Gresty Green Sidings				
TSO	5464	The Railway Age, Crewe	Stored at Gresty Green Sidings				
TSO	5494	The Railway Age, Crewe	Stored at Gresty Green Sidings				
TSO	<b>5547</b> 6501	RFS (E) Ltd, Doncaster	Stored at Healey Mills Yard				
TSO	<b>5558</b> 6521	RFS (E) Ltd, Doncaster	Stored at Healey Mills Yard				
TSO	<b>5563</b> 6527	RFS (E) Ltd, Doncaster	Stored at Healey Mills Yard				
TSO	<b>5603</b> 6500	RFS (E) Ltd, Doncaster	Stored at Healey Mills Yard				
FK	<b>13462</b> 19462 13462	The Railway Age, Crewe	Stored at Gresty Green Sidings				
FK	13467	The Railway Age, Crewe	Stored at Gresty Green Sidings				
FK	<b>13479</b> 19479 13479	The Railway Age, Crewe S	Stored at Gresty Green Sidings				

#### 3) Detail alterations

13482

FK

#### a) Mark 1 Passenger Carrying Coaching Stock

RKB	1569	Restored with BR1 h.d. bogies
RU	1933	Restored with BRII bogies (believed to have come from Exhibition
		Van 99634 which was converted from Corridor Second 25317)
FO	3106	Delete 'BN91 Set' and replace with 'Stored at Gresty Green Sidings'
FO	3109	Delete 'BN91 Set' and replace with 'Stored at Gresty Green Sidings'
FO	3112	Delete 'BN91 Set' and replace with 'Stored at Gresty Green Sidings'
TSO	4656	Restored with BR1 h.d. bogies

The Railway Age, Crewe Stored at Gresty Green Sidings

# 4) Corrections to 'Preserved Coaching Stock of British Railways - Part one'

It has now been established that all Corridor Seconds of lot 30349 were built with **BR Mk I Madison (BR II)** bogies. Thus the following changes should be made:-

- Page 9 In the section on **Bogies** the narrative regarding **BR Mk I Madison (BR II)** should have the word 'certain' deleted from the second sentence.
- Page 16 Delete the following section:- 7. BR Mark I replaced with BR Mark I Madison
- Page 42 In the details for **Lot No.** 30349 **Bogies** should be BR II and the statements '25346/47/55/62/64/66/85 rebogied with BR II bogies' and '25307/12 preserved with BR II bogies' should be deleted. It should be noted that the later statement was altered as a result of information contained in Ammendment Sheet Number Two which was subsequently found to be incorrect.

Any information for inclusion in future amendment sheets should be forwarded to:-Mr P. A. Hall, 7 Barnes Avenue, Dronfield Woodhouse, Dronfield, S18 8YF carriageconundrums@gmail.com